Behoort bij BaZ nr 236/18 Belongs to NL NtM 236/18

HP1 – Edition 2016: Correction Chapter 6.6.1.4 'Notes' HP1 – Editie 2016: Correctie Hoofdstuk 6.6.1.4 'Notes'

Delete bullit 'If a large LPG-tankerfrom this vessel' and replace by: Verwijder bullit 'If a large LPG-tankerfrom this vessel' en vervang door:

• If a large LPG-tanker is navigating the route between Wandelaar pilot station and Zee-brugge harbour, the following applies: if required the LPG-tanker must anchor at West hinder anchorage - keel clearance ≥ 15% - wind force < 14m/s - tidal stream at Zeebrugge harbour entrance < 1,5kts - visibility > 1000m - all other shipping should remain at a distance ≥ 0,5nm;